



(ಲೋಕೋಪಯೋಗಿ ಬಂದರು & ಒಳನಾಡು ಜಲ ಸಾರಿಗೆ ಇಲಾಖೆ)

ಸಂ: ಸಕಾನಿಇಂ: ಉವಿಧಾ/2014-15

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಇಂಜಿನೀಯರರವರ ಕಛೇರಿ
ಲೋಕೋಪಯೋಗಿ ಬಂ ಹಾಗೂ ಒ.ಜ.ಸಾ.ಇಲಾಖೆ,
ಉಪ ವಿಭಾಗ ಧಾರವಾಡ. 11-4-2014
ದಿನಾಂಕ :

ಗೆ,

ಕಾರ್ಯನಿರ್ವಾಹಕ ಇಂಜಿನೀಯರರು,
ಲೋಕೋಪಯೋಗಿ ಬಂ & ಒ ಜ ಸಾ ಇಲಾಖೆ,
ಧಾರವಾಡ ವಿಭಾಗ, ಧಾರವಾಡ.

ವಿಷಯ : Regarding building Safty Certificate.

ಉಲ್ಲೇಖ : ತಮ್ಮ ಕಚೇರಿ ಪತ್ರ ಸಂ : 158 ದಿನಾಂಕ: 10-04-2014.

ಮಾನ್ಯರೇ,

ಮೇಲ್ಕಾಣಿಸಿದ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ದಿನಾಂಕ: 10-04-2014 ರಂದು ಶ್ರೀಮತಿ. ಲೀಲಾವತಿ ಆರ್.

ಚರಂತಿಮಠ ಪಬ್ಲಿಕ್ ಸ್ಕೂಲ್ ಹೊಸಯಲ್ಲಾಪೂರ ಧಾರವಾಡ ಕಟ್ಟಡವನ್ನು ಪರಿಶೀಲಿಸಿದೆ. ಕಟ್ಟಡದ Stability Certificate
ನ್ನು ಈ ಮುಖಾಂತರ ತಮಗೆ ಸಲ್ಲಿಸಿದೆ.

ಅಡಕ : ಸರ್ಟಿಫಿಕೇಟು.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಇಂಜಿನೀಯರರು,
ಲೋಕೋಪಯೋಗಿ ಬಂ ಹಾಗೂ ಒ.ಜ.ಸಾ.ಇಲಾಖೆ,
ಉಪ ವಿಭಾಗ, ಧಾರವಾಡ.

೪

Date: 10-04-2014

This is to certify that the Public school building of Smt: Leelavati. R. Charantimath situated in Survey No: 164 A/1 of Hosayallapur Dharwad in Ward No: 9 is inspected by me on 10th April 2014 and found to be safe as building is constructed out of RCC frame structure and is fit for the school building usage for 40 years with necessary annual mentainance.


Assistant Executive Engineer,
Public Works, Ports & Inland Water Transport
Department Sub-Division Dharwad



